



## SHAFT SINKING AT WELLWOOD STREET FAS, AMBLE, NORTHUMBERLAND.

Client:

**Northumberland  
Water**



Shaft Sinking works underway at Wellwood Street, Amble

### PROJECT DETAILS

#### SHAFT SINKING

- 1 No finished 10.67m diameter x 9m deep caisson shaft.
- Well point dewatering

#### GROUND CONDITIONS

- Made ground, wet sand and gravel overlying firm clay to formation level.

